



Figure 3.67. Transverse cracking for I-440/I-40 (2) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.